beam data monitor

0.5s since last NuMI kicker fire - $A9 signal

222.4s since last update of beam monitoring files

Last update at: Fri Jun 10 14:37:15 2005

Please check that beam monitoring data server is running!

Increasing difference between two numbers above is indicative of the server problem

Copy (Ctrl-C) and paste (Ctrl-V) this link to your browser for instructions:

http://minos.phy.bnl.gov/software/bd/BeamData/doc/starting.txt

Send an email to Brett (bv@bnl.gov) or Rustem (rustem@fnal.gov) if you have any questions